

Court Date:	November 24 th , 2008
Defendant:	H.A.P Mechanical Services Limited
City:	London, Ontario
Site:	See charges below
Charge(s):	<p>(1) <i>Fail to Apply for Inspection</i>, Rule 2-004(1) ESC – 88 Mill St, Iderton ON – between October 20th and 25th 2007</p> <p>(2) <i>Fail To Apply For Inspection</i> – Rule 2-004 (1) ESC – 41 Piers Crescent, London ON – between June 23rd & 27th 2008</p> <p>(3) <i>Leave Hazardous Condition</i> – Rule 2-2000 ESC – 41 Piers Crescent, London ON – between June 23rd & 27th 2008</p> <p>(4) <i>Fail To Apply For Inspection</i> – Rule 2-004 (1) ESC – 1413 Aldersbrook Road, London ON – between July 21st & August 8th 2008</p> <p>(5) <i>Fail To Apply For Inspection</i> – Rule 2-004 (1) ESC – 59 Kirk Drive, London ON – between November 5th & 12th 2008</p>
Offence Date:	See charges above
Date Charge Laid:	
Counsel/agent:	Wayne Thody, President
Plea:	Guilty to counts 1-4
Disposition:	<p>Charge 1 - Fined \$2,000</p> <p>Charge 2 - Fined \$2,000</p> <p>Charge 3 – Fined \$2,000</p> <p>Charge 4 – Fined \$2,000</p>

Charge 5 - Withdrawn

Remarks:

HAP Mechanical was previously charged by ESA, after which they opened an account with ESA and began filing inspection notifications. However, the last notification, prior to this series of charges, was submitted in 2001. HAP Mechanical has again started filing notifications and has been advised that full compliance with electrical inspection requirements must be maintained or additional charges would be laid.